

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 09


Township: 7 North

Range: 1 East


Corner ID: Polk M-07

Monument Description & Remarks: Found U.S. Monument, 3" (o.d.) Pipe with Brass Cap, at East 1/4 corner of section (see below drawing for monument detail).

References on file in the County Surveyor's Office: Lee Utt survey for Clifford Hardin, recorded in Book 2, Page 317, in the Recorder's Office.



I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of Section 36-2-10, of the Indiana Code; and the above data is given under my hand and seal this 27th day of August, 1997.




Administered by: Surveyor Review Board

RECORDED
A.M. P.M. 1:43

POLK-M07

MAR 18 1985

168705

Virginia H. Adams
RECORDER MONROE CO., IND
R9-7150-15 (5/64)

BOOK 155 PAGE 517

CERTIFIED LAND CORNER RESTORATION

State of Indiana

County of Monroe

ss.

I Edmund O. Farkas, do hereby certify that on the 27 day of April, 1981, I found evidence of the reestablished the 1/4 Section corner of Sections 9 and 10 Township 7 North, Range 1 East, Second Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:

Original monument was a wood post set in 1814. Original bearing trees:

W. Oak	W. Oak
20"	20"
S14E	S82W
17 Links	47 Links

Subsequent survey by Elmer Buskirk, Monroe County Surveyor, filed in Monroe County Surveyor's Office, 1893, Book 2, Page 539. His bearing trees were:

Hickory	Red Oak
5"	10"
N70 1/2 W	N20E
47 1/2 Links	20 1/2 Links

Description of corner evidence found:


The corner location is in an open old field and no evidence was found by the corner. Southerly of the corner area a loose stone with an + on top is laying on the road bank. A former adjacent landowner said the corner used to be out in the field.

Description of monument and accessories I established to perpetuate the original location of this corner:

Based on a survey of the Section Line between Sections 9 and 10, the Forest Service set a 2 1/2" I.D. x 30" long galvanized iron pipe filled with concrete and capped with a 3" brass tablet stamped, as shown below, as the quarter corner to Sections 9 and 10 at the single proportional distance from the Section Corners, North and South.

Established the following witnesses:

B. Cherry	Yellow Poplar
10"	3"
S84E	N63E
45.2 Feet	43.4 Feet



● = Corner monument restored

□ =

Kenneth W. Anderson, USFS

Resident witnesses.....

Dated at Bedford Indiana, this 8 day of May 1981.

Signature Edmund O. Farkas Title County Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S0114

Office of.....County of.....
I hereby certify that the within instrument was filed in this office for record on the.....day of.....19....., and was filed in Book No.....Page No.....of County Records.

Signature.....Title.....

Township 7 North, Range 1 East, Section 9 & 10, Index No. G-13, Page No. 517
This instrument was prepared

Index No. G-13
(Alphabetical - Numerical)

LAND CORNER RECORD (RECTANGULAR SURVEYS)

CRS 7150-4 (Rev. 6/13/67)
GPO 806-924

T. 7N R. 1E 2nd Mer. N.F. Hoosier County Monroe State Ind.
W4 Section Corner common to sections 9 10 and

EXISTING SURVEYS

Original Government Survey

Year surveyed 1814
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species W.O. W.O.
Diameter 20" 20"
Bearing S 14 E S 82 W
Distance 17 lks 47 lks

Subsequent Corner Restoration

Year surveyed 1896 By Elmer E. Buskirk
Where filed or recorded MO. Co. ENG. OFFICE
Monument
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species HICKORY ROCK
Diameter 5" 10"
Bearing N 70.5° W N 20° E
Distance 47.5 lks 20.5 lks

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____


Evidence of Subsequent Corner Restoration Found

Year of search 1975 By T. Havrell - H. Dorton
Found 32 white stone marked on top
18" x 8" - 5" high approx 15' north of
edge of county road in open field
no trees near by

Bearing Trees, Reference Objects

open open
field field

Sec 9 Sec 10



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,
etc.

1300 2000

3. Man hours spent in search

1 hr

4. Do you think additional search might
recover evidence? Yes ☐ No ☒

5. Signature

[Signature]

Relation of Evidence to Record Features Along Section Lines

Section line to sections

Object

Record distance

Measured distance

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Stone is 15' north of road across from N. Derrard.
Mr. Derrard stated his father-in-law showed him the
stone about 40 years ago

See Corner Card 50

Perpetuation Record

Monument and accessories established. Include brief description of area.

Certified corner restoration certificate prepared:

Yes ☐ No ☐


Filed in county records at

Date

County Document No.

Identified on aerial photo No.

Which is filed at



Sketch

○ Corner ▨ F.S. Land

At time of search:

1. Did you have the record description?

Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,
etc. Land owners

3. Man hours spent in search 1 hr

4. Do you think additional search might
recover evidence? Yes ☒ No ☐

5. Signature [Signature]

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any.

Stone is

Mr. Dorr

Stone

See Cont

Monument and

Certified corner

Filed in county records at _____ Date _____ County _____

Identified on aerial photo No. _____ Which is filed at _____

T. 7 N. R. 7 E. Sec 9-10
1/4 cor. mon.
2 1/2" gal. pipe, brass cap
stamped, (9/10)
located in old field
app. 100' W. of Burgeon Rd.
and 70' W. of fence.
also property cor.